


ICS Phoenix 8000 / AFC Replacement Parts

- ICS stocks a wide range of replacement parts for the Phoenix fuel management systems. We also repair all circuit boards and components of the Phoenix 8000 fuel management system. ICS technicians have years of experience with this system, and can troubleshoot and repair them quickly. If you have a question about a Phoenix 8000 system repair, please give us a call.



Phoenix 8000 or Phoenix AFC Durakey Receptacles (P8000-DKR)

- Don't discard broken receptacles! Keep the plastic housing.
- Replace the functional part for half the cost of a new receptacle.
- New custom made receptacle contacts are superior to the original.



Phoenix 8000* Card Readers (P8000-CR-B)

- ICS Has designed a replacement card reader module specifically for Phoenix 8000 or Phoenix AFC systems.
- This model has dual read heads for superior reliability.
- Reads cards on both insertion and removal for reliable operation.



Mag Stripe Cards (P8000-CR80-A)

- Replacement CR80 style magnetic stripe cards.
- Cards can be programmed by ICS for no extra charge.
- Cards can be printed with 4 lines of customer information for no charge.



Phoenix 8000 or Phoenix AFC Keypad Upgrade (P8000-KP1-A)

- Cast metal keys. Rugged polymer housing.
- Much more durable than the original membrane keypad.
- Simple drill and bolt-on installation!
- Kit includes all instructions and hardware required for upgrade.

For more information, please visit our website at:

WWW.INTCONSYS.COM

Integrated Control Systems Inc.

1425 American Way, Cedar Hill, TX. 75104

Voice: (972) 291-6064

Fax: (972) 291-5975

WWW.INTCONSYS.COM

ICS Phoenix 8000 / AFC Replacement Parts (continued)



Phoenix AFC Keypad Adapter Plate (PAFC-KP-PLT)

- This adapter plate allows the keypad above to be used with the Phoenix AFC system.
- Kit includes all instructions and hardware required for installation.



Phoenix 8000 Replacement Display Module (P8000-LCD-A)

- Extended temperature 2 lines by 16 character backlit LCD module.
- Direct replacement for original Phoenix 8000 display.
- Kit includes all instructions and hardware required for replacement.



Phoenix 8000 Replacement Journal Printer (P8000-LX300-N)

- Epson dot matrix printer programmed and modified for use with the Phoenix 8000 or Phoenix AFC system.
- Direct replacement for original Phoenix journal printer.
- Kit includes all instructions and hardware required for replacement.


Integrated Control Systems Inc.
1425 American Way, Cedar Hill, TX. 75104
Voice: (972) 291-6064
Fax: (972) 291-5975
WWW.INTCONSYS.COM

For more information, please visit our website at:


WWW.INTCONSYS.COM

ICS Phoenix 8000 Repairs

- ICS has a full repair facility with test fixtures for the Phoenix 8000 system. We can repair all circuit boards and components. ICS technicians have years of experience with this system, and can troubleshoot and repair them quickly. If you have a question about a Phoenix 8000 system repair, please give us a call.



Phoenix 8000 CPU Board Repair



Phoenix 8000 Pump Control Board Repair



Phoenix 8000 ICB Board Repair (Any number of hoses)



Phoenix 8000 TCI Repair

Integrated Control Systems Inc.
1425 American Way, Cedar Hill, TX. 75104
Voice: (972) 291-6064
Fax: (972) 291-5975
WWW.INTCONSYS.COM

For more information, please visit our website at:

WWW.INTCONSYS.COM

ICS Phoenix AFC Repairs

- ICS can repair most components of the Phoenix AFC system. If you have a problem with a Phoenix AFC system, give us a call!




Phoenix AFC CPU Repair

(We can repair Rev. E2 or earlier)



Phoenix AFC ICB Repair

(We can repair Rev. F or earlier)



Phoenix AFC Power Supply Repair

(We can repair Rev. D or earlier)



Phoenix AFC Printer/PC Adapter Repair

Integrated Control Systems Inc.
1425 American Way, Cedar Hill, TX. 75104
Voice: (972) 291-6064
Fax: (972) 291-5975
WWW.INTCONSYS.COM

For more information, please visit our website at:

WWW.INTCONSYS.COM

ICS Phoenix System Module Repairs

- ICS can repair Phoenix system modules for much less than the cost of replacement.



Phoenix 8000 or AFC Card Reader Repair



Phoenix 8000 Journal Printer Repair (Refurbished unit)

(Journal printers are refurbished. ICS Can ship refurbished printers when a printer core is received.)

Integrated Control Systems Inc.

1425 American Way, Cedar Hill, TX. 75104

Voice: (972) 291-6064

Fax: (972) 291-5975

WWW.INTCONSYS.COM

For more information, please visit our website at:

WWW.INTCONSYS.COM